

Bulletin	Ampex 350 15 in/s NAB recording equalization
Date	15 Sept 05
Revision	1
Total pages	4

Problem

The Ampex 350 record/play electronics cannot be adjusted to provide proper record equalization when using modern tape types with 15 ips NAB equalization.

Background

Modern tape formulations have improved high-frequency response; consequently, the 15 ips NAB record equalization as implemented in the Ampex 350 record/play electronics now has too much high-frequency boost on record and cannot be adjusted for flat response.

There is no need to modify the 7.5 ips NAB record circuit as C406 should have enough adjustment range to set the record equalization properly during routine alignment.

Fix

The problem may be fixed by doing the following:

- Disconnecting the high-frequency record resonance circuit (if not previously disconnected)
- Rewiring the record EQ switch
- Installing an extra RC filter to flatten the record EQ response
- Removing extra plates in the record EQ trimmer capacitor (optional)

Required Parts

To perform this modification, you will need the following parts:

- 68K half-watt 5% resistor (preferably carbon film)
- 680 pF/500V 5% dipped silvered-mica capacitor (such as Cornell Dubilier 68PF500VJ)

IMPORTANT NOTICE AND TERMS OF USE

Full-Track Productions is not liable for any damage or injury that may result from inappropriate use of information in this document—always refer service to qualified personnel. Contents of this document copyright © 2005 by Full-Track Productions, all rights reserved. This bulletin may be distributed only if reproduced in its entirety (including this notice) without any alteration whatsoever. No fee may be charged for this bulletin nor for any information detailed here.

Procedure

Note that the following procedures assume familiarity with basic electronics repair and knowledge of standard safety protocols. They also require some mechanical dexterity and access to appropriate tools (such as temperature-controlled soldering irons). Do not undertake the following procedures if you are unqualified to do so.

Part 1: Disconnect the record resonance circuit

The Ampex 350 was introduced in 1953. At that time, the predominant magnetic recording tape used in North America was 3M "Scotch" 111; this tape had a high-frequency droop in its record response that could not be corrected with a simple R-C equalizer. Consequently, inductor L401 (20 mH) was used along with capacitors C425 and C426 to form a resonant circuit to compensate for this droop. By the late 1950s however, magnetic recording tape had improved enough so that this circuit was no longer necessary—consequently, Ampex recorders designed after approximately 1960 did not use this circuit.

- 1 Disconnect ac power from the Ampex 350 power supply and disconnect the power supply cable from the electronics chassis.
- 2 Remove the bottom cover of the record/play electronics.
- 3 Locate L401; this is the 20 mH inductor mounted on the inside rear of the front panel between the record level potentiometer and the equalization switch. The location of L401 is obvious as there are no similar components located nearby.
- 4 Cut the green wire connecting one end of the L401 to V404 (6C5/6J5). After cutting the wire, cover the cut end with a short length of heat-shrink tubing and tuck the loose wire into a convenient location.




Figure 1. Disconnecting L401





Figure 2. Record EQ switch modification

Part 2: Rewire the record switch

- 1 Locate the green wire where it joins the junction of the two trimmer capacitors (C406 and C407). Carefully unsolder the green wire at this location.
- 2 Locate the red wire where it joins the wiper terminal of the record equalization switch—this switch has several sections, so be sure to locate the correct wiper terminal. Carefully unsolder the red wire at the location.
- 3 Move the green wire to the wiper terminal of the record equalization switch. If the wire is not long enough, replace it with a longer length of green insulated wire (18 to 22-gauge stranded insulated wire is fine).
- 4 Move the red wire to the junction of the two trimmer capacitors.



Capacitor side of network goes to C406 only if you are modifying the slow speed record EQ circuit—the chassis shown here has non-standard equalization

For standard 7.5/15 ips machines, connect capacitor side of network to the left side of C407 (high speed record EQ circuit)

Figure 3. Example installation

Part 3: Install the filter

This filter is used to flatten the record response.

- 1 Solder the 68 kilohm resistor to the 680 pF silvered-mica capacitor to form a series network.
- 2 Solder the capacitor side of this network to the non-common terminal of the high-speed record EQ trimmer—this is to the left of the low-speed trimmer as you look into the underside of the record/play electronics with the rear of the chassis facing you. “Non-common” is the terminal that is not connected to the other EQ trimmer. Refer to Figure 3 for guidance.
- 3 Solder the resistor side of the network to signal ground. The most convenient way is to solder the resistor to the thin grounding wire that connects the socket grounds of the nearby octal tubes.
- 4 Check playback alignment with a standard calibration tape.
- 5 Using the tape formulation to be used for recording, adjust the record bias current, then adjust the record equalization for maximum flatness. If there is too much high-frequency boost, remove a set of plates from C407 as outlined in Part 4.

Part 4: Remove plates from C407 (optional)

If you use recording tape with good high-frequency response and a relatively thin oxide coating, you may run out of adjustment range with C407 (high-speed record EQ adjust). For example, this may occur when using Quantegy 632 with NAB 15 ips equalization. The workaround for this is to simply remove one (or more) pairs of plates from C407.

- 1 Carefully unsolder all leads from the trimmer capacitors.
- 2 Using a desoldering tool, carefully remove all solder from the capacitor terminals.
- 3 Carefully remove one or two pairs of plates. Carefully note the position of the mica insulators relative to the metal plates. Then reassemble carefully.
- 4 Reset the record equalization as described in Part 3.

Acknowledgments

Full-Track Productions would like to thank the following individuals: Jay McKnight, *Magnetic Reference Laboratory*, Mountain View, California, and Kurt Greske, Apple Valley, California, for technical suggestions; Charles Bork, Seattle, Washington, for use of his Ampex model 350 magnetic tape recorder.