

# PROFESSIONAL AUDIO DIVISION

# FIELD ENGINEERING BULLETIN

TITLE: FAULTY CONTROL SWITCHES

REF. NO. 60820 BD-8205-02 MODEL ATR-100 PAGE 1 OF 1

SUPERSEDES

DATE OF ISSUE 6/82

AMPEX PROVIDES PRODUCT IMPROVEMENT AND UPDATE INFORMATION FOR ALL AUDIO-VIDEO PRODUCTS TO ITS CUSTOMERS WORLD-WIDE. THIS SERVICE REFLECTS AMPEX'S POLICY OF AFTER SALES SUPPORT TO ENSURE THAT MAXIMUM PERFORMANCE AND RELIABILITY IS REALIZED BY OUR USERS.

## I. APPLICABILITY

ATR-100

#### II. PURPOSE

To improve the reliability of the function switches inside the control unit.

#### III.DISCUSSION

The problem is attributed to a fine powder which falls from the push buttons when they contact the plunger of the micro-switch.

To eliminate the problem we are presently installing a polyethylene sheet between the two parts.

## IV. PARTS REQUIRED

Parts for this update can be purchased through Ampex. Installation assistance can be obtained through your local Ampex regional office at current Ampex Field Engineering rates.

Oty Description Ampex P/N

1 ea. Polyethylene sheet 4291088-01

## V. PROCEDURE

Remove control unit from machine and remove the four screws on the bottom which hold the unit together. Remove the bottom cover.

Then remove the two screws which secure the printed circuit card to the top display board.

Remove and replace all faulty switches with switch, Ampex part number 119-367. Insert polyethylene sheet over PC Board which buttons go thru and reassemble unit. Unit should now be tested to make sure all functions work.