

**AMPEX****PROFESSIONAL  
AUDIO DIVISION****FIELD ENGINEERING BULLETIN**

REF. NO. 70199

MODEL ATR-100

PAGE 1 OF 1

SUPERSEDES

DATE OF ISSUE 2/78

TITLE: FAILURE OF F2 ON DC SUPPLY WHEN ACCESSORY  
IS USEDI. APPLICABILITY

ATR-100 all versions.

II. PURPOSE

F2 on the DC supply will blow when some accessories are used.

III. DISCUSSION

Due to increased current demands from the DC supply, fuse F2 which protects the +5VDC regulated supply should be changed. When an accessory such as the multipoint search to cue is used, the fuse often blows. If an accessory is used on the ATR-100, then a change must be made to the DC supply.

IV. PARTS LIST

1 each 5 amp fast-blow 250V fuse, P/N 070-072.

V. PROCEDURE

Remove F2 (3A-FB-250V) from the DC supply and replace with a 5 amp-FB-250V.